



FORD MEDIA CENTER

## Ford Issues Two Safety Compliance Recalls in North America

**DEARBORN, Mich., Oct. 11, 2016** – Ford Motor Company is issuing two safety compliance recalls in North America. Details are as follows:

### **Ford issues safety compliance recall for certain 2017 Lincoln Continental vehicles for headlamp assemblies**

Ford is issuing a safety compliance recall for approximately 1,900 2017 Lincoln Continental vehicles to inspect and, if necessary, replace headlamp assemblies. In affected vehicles, HID headlamps may have been misbuilt with LED lenses that are missing the lens optics necessary to meet turn signal visibility requirements of FMVSS 108.

Ford is not aware of any accidents or injuries associated with this issue.

Affected vehicles include certain 2017 Lincoln Continental vehicles built at Flat Rock Assembly Plant, June 14, 2016 to Sept. 23, 2016. There are approximately 1,876 vehicles affected including 1,826 in the United States, 49 in Canada and one in federalized territories.

Dealers will replace headlamp assemblies if necessary at no cost to the customer.

### **Ford issues safety compliance recall for certain 2015-16 Ford Edge vehicles to update antilock braking system (ABS) modules**

Ford is issuing a safety compliance recall for approximately 60 2015-16 Ford Edge vehicles to update antilock braking system (ABS) modules.

Incorrect ABS module software may have been loaded into some vehicles when they were in for service. The incorrect software could disable electronic stability control (ESC), engine torque control, traction control (T/C), the warning lamp/indicator, the electronic parking brake (EPB) light and the EPB drive-away release function. ABS and electronic brake distribution (EBD) remain fully functional and the EPB can be applied.

Ford is not aware of any accidents or injuries associated with this issue.

Affected vehicles include certain 2015-16 Ford Edge vehicles built at Oakville Assembly Plant, Feb. 9, 2015 to Aug. 12, 2016, which may have had software programmed during service between Aug. 6, 2016 and Sept. 28, 2016. There are approximately 59 vehicles affected including 53 in the United States, three in Canada and two in Mexico.

Dealers will replace the ABS control module or reprogram the ABS module with updated software at no cost to the customer.

## About Ford Motor Company

*Ford Motor Company (NYSE: F) is a global company based in Dearborn, Michigan, that is committed to helping build a better world, where every person is free to move and pursue their dreams. The company's Ford+ plan for growth and value creation combines existing strengths, new capabilities and always-on relationships with customers to enrich experiences for and deepen the loyalty of those customers. Ford develops and delivers innovative, must-have Ford trucks, sport utility vehicles, commercial vans and cars and Lincoln luxury vehicles, as well as connected services. Additionally, Ford is establishing leadership positions in mobility solutions, including self-driving technology, and provides financial services through Ford Motor Credit Company. Ford employs about 182,000 people worldwide. More information about the company, its products and Ford Credit is available at [corporate.ford.com](http://corporate.ford.com).*