



FORD MEDIA CENTER

Ford Issues Safety Recall in North America for Select 2018 Ford Edge and Lincoln MKX Vehicles for Door Striker Bolts

DEARBORN, Mich., Sept. 13, 2018 – Ford is issuing a recall for approximately 555 select 2018 Ford Edge and Lincoln MKX vehicles in North America to replace door striker bolts in all four doors.

In affected vehicles, some door striker bolts may be 5 millimeters shorter than the required length. In the event of a crash, a shorter bolt may allow the door to open, increasing the risk of injury. Dealers will replace door striker bolts in all four doors at no cost to customers.

Ford is not aware of any reports of accident or injury as a result of this condition.

Affected vehicles include 2018 Ford Edge and 2018 Lincoln MKX vehicles built at Oakville Assembly Plant, July 27-31, 2018.

There are approximately 555 vehicles in North America relating to this concern, with 503 vehicles in the United States and its federalized territories, 51 in Canada and one in Mexico. The Ford reference number for this recall is 18C06.

About Ford Motor Company

Ford Motor Company (NYSE: F) is a global company based in Dearborn, Michigan, that is committed to helping build a better world, where every person is free to move and pursue their dreams. The company's Ford+ plan for growth and value creation combines existing strengths, new capabilities and always-on relationships with customers to enrich experiences for and deepen the loyalty of those customers. Ford develops and delivers innovative, must-have Ford trucks, sport utility vehicles, commercial vans and cars and Lincoln luxury vehicles, as well as connected services. Additionally, Ford is establishing leadership positions in mobility solutions, including self-driving technology, and provides financial services through Ford Motor Credit Company. Ford employs about 182,000 people worldwide. More information about the company, its products and Ford Credit is available at corporate.ford.com.