



FORD MEDIA CENTER

Ford Motor Company Issues Safety Recall

DEARBORN, Mich., May 10, 2021 – Ford Motor Company is issuing a safety recall for select 2016-19 Ford Explorer vehicles for roof rail covers that may become detached from the vehicle while driving and create a hazard for others on the road. Affected Explorer series vehicles include base and XLT trim levels, as well as Police Interceptor and Explorer Sport models with roof rail covers that are painted Silver, Black or Absolute Black.

This action affects 620,483 vehicles in the U.S. and federal territories, 36,419 in Canada and 4,260 in Mexico.

Ford is not aware of any reports of accidents or injuries related to this condition.

Dealers will secure the roof rails with plastic push pins. Customer notifications will begin the week of June 28. The Ford reference number for this recall is 21S22.

About Ford Motor Company

Ford Motor Company (NYSE: F) is a global company based in Dearborn, Michigan, that is committed to helping build a better world, where every person is free to move and pursue their dreams. The company's Ford+ plan for growth and value creation combines existing strengths, new capabilities and always-on relationships with customers to enrich experiences for and deepen the loyalty of those customers. Ford develops and delivers innovative, must-have Ford trucks, sport utility vehicles, commercial vans and cars and Lincoln luxury vehicles, as well as connected services. Additionally, Ford is establishing leadership positions in mobility solutions, including self-driving technology, and provides financial services through Ford Motor Credit Company. Ford employs about 182,000 people worldwide. More information about the company, its products and Ford Credit is available at corporate.ford.com.